

Benötigtes Werkzeug:

Necessary tools:

Outil Nécessaire:






Nářadí potřebné pro montáž:

Potrzebne narzędzia:


Potrebné náradie:

Szükséges szerszámok:



Herramientas necesarias:




A










OK







DN 50




ADHESIVE/SILICONE







4,5 x 16 mm





4,5 x 16 mm





4,5 x 16 mm





!  max 0.5 mm !



!  max 0.5 mm !








!  max 0.5 mm !




4,5 x 16 mm (3 m)










B+C





OK








B+C






DN 50










C





B




max 1,2 Nm

8x
5x20mm



28 SunOptics



B+C

